

Baukastenstückliste	Benennung	Expl - Bild	Datum	Name
4000 4111 01	C12 HZ	4926 411 03	29.12.2008	Ilkou

  

The diagram shows an exploded view of a power tool assembly. The parts are numbered from 1 to 700. Several callout boxes are present, each containing a set of numbers:

- Box 1: 15, 16, 17, 18, 19
- Box 2: 20, 21, 22, 23
- Box 3: 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 36, 37, 38, 39, 40, 41
- Box 4: 7, 8, 9, 10, 11, 12, 13, 14
- Box 5: 43, 44, 45, 46
- Box 6: 47
- Box 7: 700

The assembly includes a motor (15), a gear train (16-19), a handle (20), a trigger (21), a switch (22), a battery pack (23), a gear housing (25), a gear (26), a gear housing (27), a gear (28), a gear housing (29), a gear (30), a gear housing (31), a gear (32), a gear housing (33), a gear (34), a gear housing (36), a gear (37), a gear housing (38), a gear (39), a gear housing (40), a gear (41), a motor (43), a gear housing (44), a gear (45), a gear housing (46), a handle (47), and a battery pack (700).