



WARNING: THE FOOT COVER, KEY NUMBER 21, INSULATES THE CAP SCREW, KEY NUMBER 22, MAKING IT PART OF THE DOUBLE INSULATED SYSTEM. THEREFORE, IT MUST ALWAYS BE REPLACED WHEN REPLACING PARTS OR MAKING REPAIRS TO THIS TOOL.