



Position	Amount	Type number	Description	PG
1	1	310010350	Armature compl., 230V	35
2	1	311012230	Feldpaket vollstaendig	28
3	1	344497170	Cable with plug	25
4	1	344101140	Cable sleeve	13
5	1	343362490	Cable clip	12
6	1	141117060	Self-tap. fill. h. screw	12
7	2	344498880	Strand compl.	10
8	1	315013660	Motor housing	22
9	1	343430940	Switch rod	10
10	1	343397810	Switch slide,H/L	10
12	1	344097870	Rubber bushing	10
13	1	343430930	Baffle	16
14	1	143114880	Ball bearing, 8x22x7	19
15	1	343430910	2 part motor cap	20
16	3	141113180	Self-tap. fill. h. screw	10
17	4	141117060	Self-tap. fill. h. screw	12
19	1	315202620	Bearing flange	25
22	1	344099150	Handle	19
23	1	316051580	Spindle head with Spindle stop	35
24	1	343082840	Electronic unit,230V	31
25	1	343409640	Switch	19
26	2	316046890	Brush holder compl. cut out,230V	22
27	1	316046900	Carbon brush set cut-off	22
28	1	399999990	Part not needed	
30	1	341071110	Carrier	24
31	1	344099140	Buffer	13
35	1	338057490	Rating plate	10
36	1	399999990	Part not needed	
61	1	341161360	Spindle shaft	32
62	1	143115270	Ball bearing,12x24x6	21
63	1	143111090	Ball bearing, 10x30x9	24
64	1	141180370	Retaining ring	10
65	1	143115490	Compensating washer	10
66	1	341071300	Coupling	18
70	1	143115470	Compensating washer	10
71	1	316051700	Luefter mit Staubschutzkorb	17
75	1	316059800	Spindle lock	
1001	1	338505710	Wiring diagram	

